

General Information

Public Record Posted Date: 10/1/2011

Total Number of UST Facilities: 717

Total Number of USTs: 1867

Summary Information for On-Site Inspections

Number of UST Facilities Inspected: 313

Inspection Period Dates: 10/1/2010 to 9/30/2011

Percent Compliance (Combined Measure): 91.37

Note: Tanks, facility, and on-site inspection information is based on the number of federally regulated USTs that are currently in use or temporarily out of use. On-Site inspections measure compliance with SOC-3 (SOC-1 and/or SOC 2) standards.

Summary Information for Releases

Number of Confirmed Releases: 13

Release Reporting Period Dates: 10/1/2010 to 9/30/2011

Summary Information for Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	4	30.8 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	4	30.8 %
Piping	6	46.2 %	0	0.0 %	0	0.0 %	0	0.0 %	1	7.7 %	0	0.0 %	1	7.7 %	4	30.8 %
Dispenser	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %
STP	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %
Delivery Problem	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %
Other	1	7.7 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	1	7.7 %
Unknown	2	15.4 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	0	0.0 %	1	7.7 %	1	7.7 %
Totals	13	100.0 %	0	0.0 %	0	0.0 %	0	0.0 %	1	7.7 %	0	0.0 %	2	15.4 %	10	76.9 %

= number, % = percent of total number

Note: Release, source, and cause information is based on the number of federally regulated USTs. Source and cause data were collected using inspection records.

Site-specific UST compliance and release information can be obtained by contacting the Wyoming Department of Environmental Quality Solid and Hazardous Waste Division:

phone 307-777-7752

email blucht@wyo.gov or ogilbr@wyo.gov